



1:92



Kommentar

Tekst: Lekkasje i tee



Kryssmåling utskifting av tee

A↔1: 5.2m A↔2: 8.5m